



N4986

CAUTION-LEAKING FUEL CAPS CAN CAUSE LOSS OF FUEL AND

ERRONEOUSLY HIGH FUEL QTY INDICATIONS

N4986

MAXIMUM CROSSWIND COMPONENT FOR AIRCRAFT IS 15 K

SEAT SLIP WARNING  
REMOVE AIRCRAFT SEATBELT FASTENERS  
BEFORE TAKEOFF AND LANDING

BOEING 737

BOEING 737

